

# Siemens 6GK1901-1GA00

## Ethernet Easy Strip (Fast Connect) Stripping tool



### Stripping Instructions



After consulting the scale table on the back of the cutter, mark the cable with your thumb. Insert the cable using your thumb as a guide.



Close the clamp by turning the dial, for the best results first click the dial by 2 notches.



Rotate the tool twice away from you, then close the clamp fully and rotate twice more.



Pull the stripping tool lengthways from the cable. Avoid tilting the tool as this could damage the wires inside.



Inspect the resulting cable strip, if unsatisfactory rotate or replace the blade cassette and retry.



Remove the remaining plastic foil by slitting up the cable with a small slotted screw driver. Once clear attach the stripped cable to the connector of your choice.