

Siemens 6GK1905-6AA

PROFIBUS Easy Strip (Fast Connect) Stripping tool



Stripping Instructions



① After consulting the scale table on the back of the cutter, mark the cable with your thumb. Insert the cable using your thumb as a guide



② Close the clamp by turning the dial, for the best results first click the dial by 2 notches.



③ Rotate the tool twice away from you, then close the clamp fully and rotate twice more.



④ Pull the stripping tool lengthways from the cable. Avoid tilting the tool as this could damage the wires inside.



⑤ Inspect the resulting cable strip, if unsatisfactory rotate or replace the blade cassette and retry.



⑥ Remove the remaining plastic foil by slitting up the cable with a small slotted screw driver. Once clear attach the stripped cable to the connector of your choice.